

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Mike Davis
OGM	Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0410002		
Inspection Type:	COMPLETE		
Inspection Date:	Tuesday, October 13, 2009		
Start Date/Time:	10/13/2009 8:00:00 AM		
End Date/Time:	10/13/2009 2:00:00 PM		
Last Inspection:	Monday, September 14, 2009		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Cloudy, Temp. 63 Deg. F.

InspectionID Report Number: 2158

Accepted by: jhelfric

10/29/2009

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: SUFCO MINE

Address: 397 S 800 W, SALINA UT 84654

County: SEVIER

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

25,292.43 Total Permitted	✓ Federal	✓ Underground
48.43 Total Disturbed	✓ State	☐ Surface
Phase I	☐ County	☐ Loadout
Phase II	☐ Fee	Processing
Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date

Tuesday, October 13, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0410002 Inspection Type: COMPLETE

Inspection Date: Tuesday, October 13, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	V		V	
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	V			
13.	Revegetation	✓			
14.	Subsidence Control	V			
15.	Cessation of Operations	✓			
16.a Roads: Construction, Maintenance, Surfacing		✓			
16.t	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	V			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓		~	
22.	Other	✓	. 🗆		

Permit Number: C0410002 Inspection Type: COMPLETE

Inspection Date: Tuesday, October 13, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/041/0002 was issued effective 05/21/2007 and expires 05/21/2012.

- -Certificate of Insurance policy number GL093-61-11, issued 07/31/2009 and terminates 07/31/2010.
- -UPDES permit # UT0022918 effective 04/01/2006 and expires @ midnight 04/30/2011.
- -Air Quality permit DAQE-AN0665008-06, issued May 26, 2006.
- -SPCC Plan dated July 2004. The Plan is P.E. certified, stamped, signed and dated 09/10/2007 by a Utah P.E.

2. Signs and Markers

The ID signs located at the points of public access contained the necessary information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The annual sediment pond certification for the main sediment pond and the waste rock sediment pond were done on September 30, 2008. First quarter 2009 sediment pond inspections were done on March 31, 2009. Second quarter 2009 sediment pond inspections were done on June 30, 2009.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the discharge monitoring reports for August 2009. 001A did not discharge. 002A and 003A discharged, but did not exceed any parameters.

7. Coal Mine Waste, Refuse Piles, Impoundments

The annual refuse pile inspection and certification was done on September 30, 2008. The second quarter 2009 was done on June 10, 2009. The 4th (lift or cell) is almost complete. The area is being prepared for the 5th area.

8. Noncoal Waste

The concrete walls have been pored for the noncoal waste facility.

21. Bonding and Insurance

The bond amount is \$4,439,000.00